| VISIBLE EMISSION NOTA | ATIONS | | |
|--|---|--|----------|
| Inspector: | Long | | |
| Date of Inspection: | 1 | | |
| Shift: 1 st Shift or 2 nd Sh | nift Ind | ime: 500 AM) | |
| Unit | - Visual Inspection <u>NORMAL</u> or ABNORMAL | | Comments |
| Visible Emission From Shaker | Nar | Confidence actions with the confidence of the co | |
| Visible Emission From Discharge Conveyor System | Non | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTATIONS | | | | |
|---|--|------|-------|--|
| Inspector: Ted Compto | | | | |
| Date of Inspection: | | | | |
| Shift: (1st Shift or 2nd Shift / S + Ti | me: | | | |
| - Unit Visual | | Comn | nents | |
| Inspection NORMAL | | | | |
| or <u>ABN</u> ORMAL | | | | |
| Visible Emission From Shaker | ************************************** | | | |
| Visible Emission From Discharge Conveyor System | | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTATIONS | | | |
|--|--|----------|--|
| Inspector: Ted Compton | | | |
| Date of Inspection: | | | |
| Shift: 1 st Shift or (2 nd) Shift 2nd | ime: 500 AM | | |
| - Visual | | Comments | |
| Inspection NORMAL or ABNORMAL | | | |
| Visible Emission From Shaker | Language and the first section of the section of th | | |
| Visible Emission From Discharge Conveyor System | ************************************** | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | ATIONS | | | |
|------------------------------|------------|---------------|----------|--|
| Inspector: | | | | |
| D+402 | (| | | |
| Date of Inspection: | | | | |
| 10 | 12/11 | | | |
| Shift: (1 Shift) or 2nd Sh | nift Ti | ime: | | |
| | | <u>CIT:00</u> | | |
| L. Unit | Visual | | Comments | |
| | Inspection | ĺ | | |
| | NORMAL | | | |
| | or | <u></u> | | |
| | ABNORMAL | | | |
| Visible Emission From Shaker | Alma | yalayangarika | | |
| | 100K | | | |
| Visible Emission From | | Toward. | | |
| Discharge Conveyor System | Nac | | | |
| | 18010 | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | ATIONS | | _ | |
|--|----------------------|--|----------|--|
| Inspector: | Conston | | | |
| Date of Inspection: | 10/3/4 | | | |
| Shift: 1 st Shift or 2 nd Sh | iift dad Ti | me: 500AM | | |
| Unit | - Visual | | Comments | |
| | Inspection NORMAL | . , | | |
| | or ABNORMAL | - | - | |
| Visible Emission From Shaker | Nor | g of the state of | | |
| Visible Emission From Discharge Conveyor System | Nor | The company and the State Company and the Comp | | |


- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | TIONS | | | | |
|--|--|---------------|-------|----------|--|
| Inspector: | A | | | | |
| Date of Inspection: | 10/3/11 | | | | |
| Shift: (1 st Shift) or 2 nd Sh | ift Ti | ime: () 17:00 | > | | |
| Unit | Visual Inspection NORMAL or ABNORMAL | | | Comments | |
| Visible Emission From Shaker | NOR | ATOL | NWOOD | | |
| Visible Emission From Discharge Conveyor System | Noe | (4 | £ 4 | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | TIONS | | | |
|--|--|--------------|----------|--|
| Inspector: RICK F | Alone | | | |
| Date of Inspection: | /11 | | | |
| | nift Ti | me: 5:00 A M | | |
| Unit | - Visual Inspection NORMAL or ABNORMAL | | Comments | |
| Visible Emission From Shaker | NOR | | | |
| Visible Emission From Discharge Conveyor System | NOR | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.




| VISIBLE EMISSION NOTA | TIONS | | | |
|--|-----------------|-------------|----------|---|
| Inspector: | - 10- | | | |
| the janua He | ryancez_ | | | |
| Date of Inspection: | | | | |
| Shift: 1 st Shift or 2 ^{hd} Shi | ft 15T Ti | me: | | |
| | named and | <u> ODW</u> | | |
| . Unit | - Visual | parties. | Comments | ' |
| The second of th | Inspection | | | |
| The state of the s | NORMAL | | | |
| | gr | - | | |
| | <u>ABNORMAL</u> | | | |
| Visible Emission From Shaker | NOR | | | |
| Visible Emission From | | | | |
| Discharge Conveyor System | MOR | | | |

• Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

• Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOT | ATIONS | | | |
|--|--------------------------------------|--|----------|--|
| Inspector: Rick C | ALOMO | | | |
| Date of Inspection: 10/1 | 0/11 | | | |
| Shift: 1 st Shift or 2 nd Sh | ift 2nd T | ime: BOOAM | | |
| Unit | Visual Inspection NORMAL or ABNORMAL | | Comments | |
| Visible Emission From Shaker | NOR | ************************************** | | |
| Visible Emission From Discharge Conveyor System | NOR | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



| VISIBLE EMISSION NOTATIONS | | | |
|---|------|----------|--|
| Inspector: All andro Hernandez | | | |
| Date of Inspection: | | | |
| Shift: 1 st Shift or 2 nd Shift 5 T | ime: | | |
| Unit Visual Inspection NORMAL or ABNORMAL | | Comments | |
| Visible Emission From Shaker | | | |
| Visible Emission From Discharge Conveyor System | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | ATIONS | | | |
|--|--|---|----------|--|
| Inspector: Rick | PALOMO | | | |
| Date of Inspection: 10/6 | /11 | | | |
| Shift: 1 st Shift or 2 nd Sh | end Ti | me: 5:00Am | | |
| Unit | Visual Inspection NORMAL or ABNORMAL | | Comments | |
| Visible Emission From Shaker | NOR | , valgailleon ann ann an deach ann ann ann an ann ann ann ann ann ann | | |
| Visible Emission From Discharge Conveyor System | NOR | -making plants of the later and the later | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | ATIONS | | | |
|--|----------------------|-------------|----------|--|
| Inspector: Alexadic He | rnandez | | | |
| Date of Inspection: | -11 | | | |
| Shift: 1 st Shift or 2 nd Sh | nift pot Ti | ne: 500M | | |
| Unit | - Visual | | Comments | |
| | Inspection NORMAL | | | |
| The state of the s | or ABNORMAL | | - | |
| Visible Emission From Shaker | NOR | | | |
| Visible Emission From | | | | |
| Discharge Conveyor System | NOR | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOT | ATIONS | | | |
|--|-----------------------------------|-----------|----------|--|
| Inspector: | Control | | | |
| Date of Inspection: | 17/11, | | | |
| Shift: 1 st Shift or (2 nd)Sh | lift Ind | me: 500AM | | |
| | Visual | | Comments | |
| | Inspection <u>NORMAL</u> or | | | |
| Constitution of the Consti | ABNORMAL | | | |
| Visible Emission From Shaker | Nov | | | |
| Visible Emission From Discharge Conveyor System | Nar | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | TIONS | | _ | |
|---|---|---|----------|--|
| Inspector: | | | | |
| | 10107 | | | |
| Date of Inspection: | | | | |
| 10-7-1 | | | | |
| Shift: 1 st Shift or 2 nd Shi | | me: | | |
| | James | <u> </u> | | |
| Unit | Visual | , | Comments | |
| | Inspection | | | |
| | NORMAL | | • | |
| | or | , | • | |
| | ABNORMAL | | | |
| Visible Emission From Shaker | | | | |
| | NOR | | | |
| Visible Emission From | | | | |
| Discharge Conveyor System | | | | |
| | NOK | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | TIONS | | | |
|--|-------------------------------|--|----------|--|
| Inspector: | Compten | | | |
| Date of Inspection: | 3/11/ | | | |
| Shift: 1 st Shift or 2 nd Sh | ift Ti | me: 500 AV1 | | |
| Umt | Visual | , | Comments | |
| | Inspection NORMAL or ABNORMAL | | | |
| Visible Emission From Shaker | Nas | The state of the s | | |
| Visible Emission From Discharge Conveyor System | Non | All from the transport of the transport | | |

- Visible inspection must be performed during nermal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE | EEMIS | SION N | ATO | TIONS |
|---------|-------|--------|-----|-------|
|---------|-------|--------|-----|-------|

| Inspector: | | | | |
|--|--|--|----------|---|
| Date of Inspection: | | | | |
| Shift: 1 st Shift or 2 nd Sh | ift T | ime: | | |
| Section 20 mit | Visual Inspection NGRMAL or ABNORMAL | | Comments | *************************************** |
| Visible Emission From Shaker | NOR | | | |
| Visible Emissi●n From Discharge Conveyor System | NOR | consistent and analysis of the second and the secon | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | TIONS | | | |
|--|-----------------------------------|--|----------|--|
| Inspector: | 1 Conston | | | |
| Date of Inspection: | 19/1/ | | | |
| Shift: 1 st Shift or (2 nd Sh | iift Ind Ti | me: 500AM | | |
| Unit- | - Visual | | Comments | |
| | Inspection <u>NORMAL</u> or | | | |
| Constitution of the second sec | ABNORMAL | | | |
| Visible Emission From Shaker | Nor | The same and the s | | |
| Visible Emission From Discharge Conveyor System | Nor | - | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.







| VISIBLE EMISSION NOTA | ATIONS | | | |
|--|------------------------|--|----------|--|
| Inspector: | | | | |
| Date of Inspection: | 1.) O(1es | 3 / [[| | |
| Shift: (Shift) or 2 nd Sh | nift Ti | me: 6:00cm | | |
| Unit | Visual | | Comments | |
| | Inspection NORMAL | | | |
| | or <u>ABN</u> ORMAL | | | |
| Visible Emission From Shaker | Nes | COLUMN CONTRACTOR CONT | | |
| Visible Emission From Discharge Conveyor System | Noc | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTATI | ONS, | | | |
|--|----------------------|--|----------|--|
| Inspector: Ted Cow | roton | | | |
| Date of Inspection: 10/10/1/ | | | | |
| Shift: 1 st Shift or 2 nd Shift | In J | me: 500AM | | |
| and the state of t | - Visual | | Comments | |
| | Inspection NORMAL | | | |
| | or ABNORMAL | , | • | |
| Visible Emission From Shaker | Nor | Метиненный податываем на предоставления податываем податываем на предоставления на | | |
| Visible Emission From Discharge Conveyor System | Nev | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | TIONS | | | |
|--|------------|-------------|----------|--|
| Inspector: | 5 | | | |
| Alexander Herman | <u>d+7</u> | | | |
| Date of Inspection: | • | | | |
| <u> </u> | | | | |
| Shift: 1st Shift or 2nd Sh | ift Ti | me: | | |
| | <u> </u> | <u>Dana</u> | | |
| Unit | Visual | | Comments | |
| n an manatan kana waka la | Inspection | | | |
| The state of the s | NORMAL | • | | |
| Control of the second of the s | or | | • | |
| | ABNORMAL | | | |
| Visible Emission From Shaker | | | | |
| | NOR | | | |
| Visible Emission From | | | | |
| Discharge Conveyor System | NOR | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | ATIONS | | | |
|--|---|---|----------|--|
| Inspector: Red PA | Hore | | | |
| Date of Inspection: | - 111 | | | |
| Shift: 1 st Shift or 2 nd Sh | ift Ti | me: Glocan | | |
| Unit | - Visual Inspection <u>NORMAL</u> or <u>ABN</u> ORMAL | | Comments | |
| Visible Emission From Shaker | \$ 300(| ^D BBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBB | | |
| Visible Emission From Discharge Conveyor System | NOR | Manufacture and a second and a | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | TIONS | | | |
|--|------------|-------------|----------|--|
| Inspector: | , | | | |
| | nandez | ~~~~ | | |
| Date of Inspection: | | | | |
| 10-11- | | | | |
| Shift: 1 st Shift or 2 nd Sh | ift Ti | me: | | |
| | Sit | <u> 59M</u> | | |
| Unit | Visual | | Comments | |
| The second of th | Inspection | | | |
| The state of the s | NORMAL | | | |
| | _i or | - | | |
| See a second sec | ABNORMAL | | | |
| Visible Emission From Shaker | | | | |
| | Nok | | | |
| Visible Emission From | | | | |
| Discharge Conveyor System | 5 m (*) | | | |
| | NOK | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | TIONS | | | |
|--|---|--|----------|--|
| Inspector: RICK PAL | omo | | | |
| Date of Inspection: | | | | |
| Shift: 1 st Shift or 2 nd Sh | ift Ti 2nd | me: 5:00AM | | |
| Unit. | Visual Inspection <u>NoRMAL</u> or ABNORMAL | | Comments | |
| Visible Emission From Shaker | NOR | | · | |
| Visible Emission From Discharge Conveyor System | NOR | ************************************** | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTAT | IONS | | | |
|---|--|-----|----------|--|
| Inspector: Alexendro Her | mande Z | | | |
| Date of Inspection: | . 3 | | | |
| 10-12 | - Ton- | | | |
| Shift: 1 st Shift or 2 nd Shift | Time: | 50m | | |
| Unit | Visual Inspection NORMAL or ABNORMAL | · | Comments | |
| Visible Emission From Shaker | NOR | | | |
| Visible Emission From Discharge Conveyor System | NOR | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTATIO | NS | | | | |
|--|--|--|---|----------|--|
| Inspector: Rick Acome | 9 | | | | |
| Date of Inspection: 10/13/11 | | | | | |
| Shift: 1 st Shift or 2 nd Shift | nd Tin | me: 5:00 AM | | | |
| The state of the s | Visual nspection NORMAL or BNORMAL | | | Comments | |
| Visible Emission From Shaker | or | And the through the first throughout the second sec | ÷ | | |
| Visible Emission From Discharge Conveyor System | WR | No de la constant de constant | 5 | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | TIONS | | | |
|--|---|----------|----------|--|
| Inspector: Alexandro + | 18(Nondes | | | |
| Date of Inspection: | g contract. | | | |
| Shift: 1 st Shift or 2 nd Sh | lift ST Ti | me: 5 PW | | |
| - Unit | - Visual Inspection <u>NORMAL</u> or ABNORMAL | | Comments | |
| Visible Emission From Shaker | NOR | | | |
| Visible Emission Fr∙m Discharge Conveyor System | NOR | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | TIONS | | | |
|--|--|--|----------|--|
| Inspector: | PALOMO | | | |
| Date of Inspection: | 4/11 | | | |
| Shift: 1 st Shift or 2 nd Sh | ift' T 2nd | ime: 5800 AM | | |
| Unit | Visual Inspection NORMAL or ABNORMAL | | Comments | |
| Visible Emission From Shaker | NOR | * ************************************ | | |
| Visible Emission From Discharge Conveyor System | NOR | . And the second | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | TIONS | | | |
|--|---|-------------|---------------|--|
| Inspector: Alexandro He | mande z | | | |
| Date of Inspection: | 1 | | | |
| Shift: 1 st Shift or 2 nd Sh | ift Ti | me: 5000 | | |
| Umit | - Visual Inspection <u>NORMAL</u> or ABNORMAL | | Comments - | |
| Visible Emission From Shaker | NOR | | | |
| Visible Emission From Discharge Conveyor System | NOR | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTATION | VS / | | | |
|---|---------------------|--|----------|--|
| Inspector: Ted Com | iton | | | |
| Date of Inspection: | 7 | | | |
| Shift: 1 st Shift or 2 nd Shift | Tim | 1e: 500AW1 | | |
| | Visual | | Comments | |
| | nspection NORMAL | | | |
| | or NORMAL | ч. | • | |
| Visible Emission From Shaker | Vor | | | |
| Visible Emission From | | | | |
| Discharge Conveyor System | | ** > calculate (In CEX) and the color (In Cex) and the calculate of CEX (In Cex) an | | |

 Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

• Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.







| VISIBL | E E | MISSION | NOTATIONS |
|--------|-----|---------|------------------|
|--------|-----|---------|------------------|

| Inspector: | | | | |
|--|--|-------|----------|--|
| Date of Inspection: | | | | |
| Shift: 1 st Shift or 2 nd S | hift T | lime: | | |
| White construction and the construction of the | Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL | | Comments | |
| Visible Emission From Shaker | | | | |
| Visible Emission From Discharge Conveyor System | | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | ATIONS | | | |
|--|----------------------|--|--|--|
| Inspector: | Consto | ✓ · | | |
| Date of Inspection: | 6/110 | | | |
| Shift: 1 st Shift or (2 nd)Sh | ift 2nd Ti | me: 500AM | | |
| Called Salumita | Visual | | Comments | |
| | Inspection NORMAL | | | |
| Visible Emission From Shaker | or ABNORMAL | | - | |
| Visible Emission From Shaker | Nov | Name of Afficial Parties are wanter an appendiction to the parties of the production of the parties of the part | | |
| Visible Emission From Discharge Conveyor System | 1/20 | | one production and the contract of the contrac | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.





| VISIBLE EMISSION NOTA | ATIONS | | | |
|--|-----------------------------------|--|----------|--|
| Inspector: | M. Jams | | | |
| Date of Inspection: | | | | |
| Shift: 1 st Shift or 2 nd Sh | nift Ti | me: Sp | | |
| Unit | Visual | | Comments | |
| | Inspection <u>NORMAL</u> or | | | |
| Visible Emission From Shaker | ABNORMAL | - Allegarian and an analysis of the second | | |
| | Voc | | | |
| Visible Emission From Discharge Conveyor System | Nor | Management and the second seco | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | ATIONS | | | |
|--|----------------------|---|----------|--|
| Inspector: Ted Co | mpton | | | |
| Date of Inspection: | /// | | | |
| Shift: 1 st Shift or (2 nd)Sh | lift 2nd Ti | me: 560 AM | | |
| | - Visual | | Comments | |
| | Inspection NORMAL | | | |
| | or ABNORMAL | · | - | |
| Visible Emission From Shaker | Nov | general and the state of the st | | |
| Visible Emission From Discharge Conveyor System | Nov | * \$50mm_manuscriptor_education_educa | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | TIONS | | _ | |
|--|---|--|----------|--|
| Inspector: | 100000000 | | · | |
| Date of Inspection: | 7-11 | Honora and a second | | |
| Shift: 1 st Shift or ^{2nd} Sh | ift Sin Ti | me: 50m | | |
| Unit | Visual Inspection <u>NORMAL</u> or ABNORMAL | | Comments | |
| Visible Emission From Shaker | NOR | | | |
| Visible Emission From Discharge Conveyor System | NOR | | | |

 Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

 Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTATIONS | | | | | |
|--|--|----------|--|--|--|
| Inspector: Rick PALOMO | | | | | |
| Date of Inspection: | | | | | |
| Shift: 1 st Shift or 2 nd Shift; | Time: 5,004M | | | | |
| Umit Vist Inspec NORN or ABNOR | ition <u>/iAL</u> | Comments | | | |
| Visible Emission From Shaker | *Milliotheropathylandschilde | | | | |
| Visible Emission From Discharge Conveyor System NGR | San Contraction of the Contracti | | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTATIONS | | | | | |
|--|--|------------|----------|--|--|
| Inspector: Rick PA | + Cono | | | | |
| Date of Inspection: | 9/11 | | | | |
| Shift: 1 st Shift or 2 nd Sh | nift and Ti | me: 5100AM | | | |
| uni | Visual Inspection | | Comments | | |
| | <u>NØR</u> MAL or ABN ORMAL | | | | |
| Visible Emission From Shaker | NOR | | | | |
| Visible Emission From Discharge Conveyor System | 10 5 m2 1 | | | | |
| | 1001 | | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

 Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- background.

| VISIBLE EMISSION NOTATIONS | | |
|---|--|----------|
| Inspector: Tel Compton | | |
| Date of Inspection: | | |
| Shift: (1 st)Shift or 2 nd Shift | Time: 1700 | |
| Umit Visual Inspection NORMAL or ABNORMAL | | Comments |
| Visible Emission From Shaker | The state of the s | |
| Visible Emission From Discharge Conveyor System | To the Auditor construction of | |

• Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

cause the greatest emissions.

Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | TIONS | | | |
|--|--|--|----------|--|
| Inspector: Rick f | ALono | | | |
| Date of Inspection: | 20/11 | | | |
| Shift: 1 st Shift or 2 nd Sh | nift 2nd Ti | me: 5:00AM | | |
| Unit | Visual | | Comments | |
| | Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL | | | |
| Visible Emission From Shaker | NOR | Manufacturing and an action of the second se | | |
| Visible Emission From Discharge Conveyor System | NOR | ************************************** | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to
- cause the greatest emissions.

 Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTAT | TONS | | | |
|--|---|--|----------|--|
| Inspector: Ted Comp | Hom | | | |
| Date of Inspection: | / | | | |
| Shift: (1 st Shift or 2 nd Shift | t Ti | me: 1700 | | |
| - Unit | - Visual Inspection <u>NORMAL</u> or ABNORMAL | | Comments | |
| Visible Emission From Shaker | Nor | 4 disease en agrana compania de mandra de consumero en | | |
| Visible Emission From Discharge Conveyor System | Nac | Chambana ghanna ann ann an ann an ann ann ann ann | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to
- cause the greatest emissions.

 Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.







| VISIBLE EMISSION NOT | TIONS | | | |
|--|----------------------------|--|----------|--|
| Inspector: Rick PA | Lono | | | |
| Date of Inspection: 10/2 | t/ii | | | |
| Shift: 1 st Shift or 2 nd Sh | ift Ti 2nd | me: 5°00 | | |
| - Unit | Visual | | Comments | |
| | Inspection NORMAL or | | | |
| Visible Emission From Shaker | ABNORMAL | | <u> </u> | |
| Visible Emission From Chanci | NOR | **Options/commissions/commission/ | | |
| Visible Emission From Discharge Conveyor System | NOR | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- **Opacity** is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.





| VISIBLE EIMISSION NOTA | TIONS | | | |
|--|--------------------------------------|--|----------|--|
| Inspector: | aten | | | |
| Date of Inspection: | / | | | |
| Shift: 1 st Shift or 2 nd Sh | ift Ti | ime: 1700 | | |
| Unit | Visual Inspection NORMAL or ABNORMAL | | Comments | |
| Visible Emission From Shaker | Nov | | | |
| Visible Emission From Discharge Conveyor System | Nel | VIII ACTION CONTROL OF | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: | U/Jd// | Shift: 1st Shift or 2nd Shift Time:

| | / | 5,00 m |
|---|--|----------|
| Unit | Visual | Comments |
| | Inspection <u>NOR</u> MAL or ABNORMAL | |
| Visible Emission From Shaker | Non | |
| Visible Emission From Discharge Conveyor System | Noc | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTATIONS | ; | | | |
|---|--|--|-----------|---|
| Inspector: Ted Compt | ton | | | |
| Date of Inspection: | | | | |
| Shift: 1 st Shift or 2 nd Shift | Ti | me: 1700 | | |
| Insp No | isual pection <u>RMAL</u> gr ORMAL | | Comments | |
| Visible Emission From Shaker No. | | The second secon | garante : | |
| Visible Emission From Discharge Conveyor System | | | | · |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS

| | | | 1 | |
|--|------------------------------|--|----------|--|
| Inspector: | Torre | | | |
| Date of Inspection: | 10, | (231 11 | | |
| Shift: 1 st Shift or 2 nd Sh | nift Ti | me: Siocan | | |
| Unit | Visual | | Comments | |
| | Inspection <u>NOR</u> MAL | | | |
| | or <u>ABN</u> ORMAL | | | |
| Visible Emission From Shaker | Noc | - Constitution of the Cons | | |
| Visible Emission From | 6 | | | |
| Discharge Conveyor System | Noc | Constant of the Constant of th | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTAT | TIONS | | | |
|---|-----------------------------|--|----------|--|
| Inspector: Ted C. | mpton | , | | |
| Date of Inspection: | /1 | | | |
| Shift: 1 st Shift or 2 nd Shift | ft Ti | me: (760) | | |
| C. July Sc., Unit | Visual | | Comments | |
| | Inspection <u>NORMAL</u> | | | |
| | or ABNORMAL | | • | |
| Visible Emission From Shaker | Nor | The configuration and the configuration of the conf | | |
| Visible Emission From | | | | |
| Discharge Conveyor System | No | of Transport August Statements (see the statement of the | - | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA: | TIONS | | |
|---|---|---|----------|
| Inspector: RICK PA | +Lomo | | |
| Date of Inspection: | 8/11 | | |
| Shift: 1 st Shift or 2 nd Shi | ft and Ti | ime: 5000 AM | |
| Unit | Visual Inspection <u>NORWAL</u> or ABNORMAL | | Comments |
| Visible Emission From Shaker | NOR | **Processon department | |
| Visible Emission From Discharge Conveyor System | NOR | - And Control of the | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | ATIONS | | | |
|--|--|--|----------|--|
| | noton | | | |
| Date of Inspection: 16/24 | 12 | | | |
| Shift: 1 st Shift or 2 nd Sh | nift Ti | me: 1700 | | |
| | Visual Inspection <u>NOR</u> MAL or ABNORMAL | | Comments | |
| Visible Emission From Shaker | Nor | | | |
| Visible Emission From Discharge Conveyor System | Nor | e in the contraction and the investment of the contraction of the cont | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTATIONS | | _ | |
|---|--|----------|--|
| Inspector: Ted Corpton | | | |
| Date of Inspection: 10 / 25/// | | | |
| | ime: 1760 | | |
| Winit Visual Inspection NORMAL OF ABNORMAL | | Comments | |
| Visible Emission From Shaker | and the state of t | | |
| Visible Emission From Discharge Conveyor System | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.







| VISIBL | F | FM | ISSIC | N NC | OTAI | CIONS |
|--------|---|-------|-------|--------|--------------|-------|
| VIOIDL | | T-181 | | 714 IN | \mathbf{c} | |

| AIDIDEE FINIDOIGH HOLY | THONG | | _ | |
|--|---|--|----------|--|
| Inspector: Rick PA | +LOMO | | | |
| 7 2000 | 5/11 | | | |
| Shift: 1 st Shift or 2 nd Sh | oift Ti | me: 5800 AM | | |
| Unit | Visual Inspection <u>NORMAL</u> or <u>ABN</u> ORMAL | | Comments | |
| Visible Emission From Shaker | NOR | , and the second control of the second contr | | |
| Visible Emission From Discharge Conveyor System | NOR | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | ATIONS | | | |
|--|---|--|----------|--|
| Inspector: Ted (cm | pton | | | |
| Date of Inspection: | 7 | | | |
| 05 10/46/9 | | | | |
| Shift: 1 st Shift or 2 nd Sh | rift Ti | me: 1700 | | |
| . Unit | - Visual Inspection <u>NORMAL</u> or ABNORMAL | | Comments | |
| Visible Emission From Shaker | Nor | United and the processing control and the second of the Control and the Contro | | |
| Visible Emission From Discharge Conveyor System | Nor | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTA | ATIONS | | | |
|--|------------------------------|---|----------|--|
| Inspector: RICK PAL | one | | | |
| Date of Inspection: | 7/11 | | | |
| Shift: 1 st Shift or 2 nd Sh | ift Ti 2nd | me: 5:00AM | | |
| Unit | Visual | | Comments | |
| | Inspection <u>NOR</u> MAL | | | |
| | or <u>ABN</u> ORMAL | | | |
| Visible Emission From Shaker | NOR | **eastmanteterprise************************************ | | |
| Visible Emission From | | | | |
| Discharge Conveyor System | NOR | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOT | ATIONS | | | |
|--|--------------------------------------|--|----------|--|
| Inspector: | Compton | | | |
| Date of Inspection: 10/2 | 7/11 | | | |
| Shift: (1 st)Shift or 2 nd Sh | rift T | ime: 170 0 | | |
| e de la composición della comp | Visual Inspection NORMAL or ABNORMAL | | Comments | |
| Visible Emission From Shaker | Nox | -conditional principle and property and p | | |
| Visible Emission From Discharge Conveyor System | Nov | *Acceptable of the Section of the Se | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



| VISIBLE EMISSION NOTA | ATIONS | | | |
|--|---|--|----------|--|
| Inspector: Ted Comp | pten | | | |
| Date of Inspection: 10/28 | 11/ | | | |
| Shift: 1st Shift or 2nd Sh | nift Ti | me: 1700 | | |
| Unit | - Visual Inspection <u>NORMAL</u> or ABNORMAL | | Comments | |
| Visible Emission From Shaker | Nor | en single dispersion delle | | |
| Visible Emission From Discharge Conveyor System | Nec | | | |

- Visible inspection must be perfermed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.





| VISIBLE EMISSION NOTAT | IONS | | | | |
|---|------------------|--|------------------|-----|-----|
| Inspector: | M | -000 | | | |
| Date of Inspection: | 7 7 1 7 7 | 3(16) | | | |
| Date of Inspection. | _ 10/2c | 1/1/ | | | |
| Shift: 1 st Shift or 2 nd Shift | Tim | A . | | | |
| The Write | Visual | | Comments | | |
| | Inspection | | John Mark | | , |
| | NORMAL | | | | . : |
| | or | | | , , | |
| | <u>ABN</u> ORMAL | | | | |
| Visible Emission From Shaker | 1/-0 | participation of the state of t | | | |
| | <u> </u> | <u> </u> | | | |
| Visible Emission From | 1/20 | | | | |
| Discharge Conveyor System | V(){ | And the state of t | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

| VISIBLE EMISSION NOTATIONS | | | |
|---|---|----------|--|
| Inspector: Ted Campley | | | |
| Date of Inspection: | | | |
| | Time: 1700 | | |
| Unit Visual Inspection NORMAL or ABNORMAL | | Comments | |
| Visible Emission From Shaker | Philippe and health represents the state of | | |
| Visible Emission From Discharge Conveyor System | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.








| VISIBLE EMISSION NOTA | ATIONS | | | | |
|--|----------------------|--|---------------------------------------|-------|---|
| Inspector: RICK PAL | omo | | | | |
| Date of Inspection: | | | | | |
| Shift: 1 st Shift or 2 nd Sh | ift Ti 20d | ime: 5800 AM | | | |
| Unit | Visual | | Comments | | - |
| | Inspection NORMAL or | | | + 1 + | |
| Visible Emission From Shaker | ABNORMAL | | · · · · · · · · · · · · · · · · · · · | | |
| Visible Emission From Snaker | NOR | ************************************** | | | |
| Visible Emission From Discharge Conveyor System | A 3 -3/2 | and the state of t | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



| VISIBLE EMISSION NOTA | ATIONS | | | | |
|--|------------------------------|----------|----------------|----------|--|
| Inspector: | 7 1 | | | | |
| 100 | EXPTON | | | | |
| Date of Inspection: 10/30 | 11 | | | | |
| Shift: 1 st Shift or 2 nd Sh | nift Ti | me: (700 | | | |
| Unit | Visual | | i iki talahati | Comments | |
| | Inspection <u>NOR</u> MAL | | | | |
| | or <u>ABN</u> ORMAL | | | | |
| Visible Emission From Shaker | Nov | | | | |
| Visible Emission From | | | | | |
| Discharge Conveyor System | Nor | | . | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.





| VISIBLE EMISSION NOTA | TIONS | | | |
|---|-------------------------------|--|----------|--|
| Inspector: Ted Com | ot, n | | | |
| Date of Inspection: | /11 | | | |
| Shift: (1 st Shift or 2 nd Sh | nift Ti | me: (700 | | |
| Unit | Visual | | Comments | |
| | Inspection NORMAL or ABNORMAL | | | |
| Visible Emission From Shaker | Nor | A And in the supposed that the first of the supposed to the su | | |
| Visible Emission From Discharge Conveyor System | Nor | | | |

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.